

Test Report

 Number
 :
 TWNC00740349
 Date
 :
 Nov 05, 2018
 Output
 Output<

Applicant:	Infinity Foils Inc.	
	9090 Nieman Road Overland Park Kansas USA	

Sample Description:

One (1) group of submitted samples said to be :				
Sample I	Description	: Hot Stamping Foil		
Style / It	em No.	: MX, HR, MB, MD, MSD, MSF		
Date Sar	nple Received	: Oct 22, 2018		
Date Tes	st Started	: Oct 22, 2018		

Test Conducted :

As requested by the applicant, for details please refer to attached pages.

Conclusion:

CONClusion.		
Tested Sample	<u>Standard</u>	<u>Result</u>
Submitted Samples	Phthalates Content — As Per US 16 CFR Part 1307 for Prohibition of Children's Toys and Child Care Articles Containing Specified Phthalates	
	 Total Lead (Pb) Content In Non-Surface Coating Materials (Substrate) As Per U.S. Consumer Product Safety Improvement Act 2008, Title I, Section 101 	Pass

Authorized By: On behalf of Intertek Testing Service Taiwan Limited al Matt Wang

Intertek Testing Services Taiwan Ltd. 全國公證檢驗股份有限公司 8F., No. 423, Ruiguang Rd., Neihu District, Taipei, 11492, Taiwan, R.O.C. 11492 台北市內湖區瑞光路 423 號 8 樓

Signed by:

homasChou

Thomas Chou Manager

Page 1 of 3



Tel: (+886-2) 6602-2888 · 2797-8885 Fax: (+886-2) 6602-2420 www.intertek-twn.com

Matt Wang Sr. Manager





Test Conducted :

1. Phthalates Content

With reference to CPSIA Test Method: CPSC-CH-C1001-09.3, by solvent extraction and Gas Chromatography-Mass Spectrometer (GC-MS) analysis.

Compound	<u>Result (%)</u> Golden/coppery plastic film	<u>Limit (%)</u>
	Golden/coppery plastic him	
Di(2-ethyhexyl) phthalate (DEHP)	ND	0.1
Dibutyl phthalate (DBP)	ND	0.1
Benzyl butyl phthalate (BBP)	ND	0.1
Di-iso-nonyl phthalate (DINP)	ND	0.1
Di-iso-butyl phthalate (DIBP)	ND	0.1
Di-n-pentyl phthalate (DPENP)	ND	0.1
Di-n-hexyl phthalate (DHEXP)	ND	0.1
Dicyclohexyl phthalate (DCHP)	ND	0.1

Remarks: % = Percentage based on weight of tested sample ND = Not detected Detection limit = 0.005% (for each compound)

2. Total Lead (Pb) Content In Non-Surface Coating Materials (Substrate)

According to CPSIA Test Method: CPSC-CH-E1002-08.3(non-metal) and CPSC-CH-E1001-08.3(metal), by acid digestion and Atomic Absorption Spectrophotometer (AAS) analysis.


<u>T</u>	ested Sample	<u>Result (ppm)</u>	<u>Limit (ppm)</u>
Golden/	coppery plastic film	ND	100
Remarks:	ppm = Parts per million = ND = Not detected Detection limit = 20 ppm		



8F., No. 423, Ruiguang Rd., Neihu District, Taipei, 11492, Taiwan, R.O.C. 11492 台北市內湖區瑞光路 423 號 8 樓 Tel: (+886-2) 6602-2888 · 2797-8885 Fax: (+886-2) 6602-2420 www.intertek-twn.com



Sample photo:



End of Report

Except where explicitly agreed in writing, all work and services performed by Intertek is subject to our standard Terms and Conditions which can be obtained at our website: <u>http://www.intertek-twn.com/terms/</u>. Intertek's responsibility and liability are limited to the terms and conditions of the agreement.

This report is made solely on the basis of your instructions and / or information and materials supplied by you and provide no warranty on the tested sample(s) be truly representative of the sample source. The report is not intended to be a recommendation for any particular course of action, you are responsible for acting as you see fit on the basis of the report results. Intertek is under no obligation to refer to or report upon any facts or circumstances which are outside the specific instructions received and accepts no responsibility to any parties whatsoever, following the issue of the report, for any matters arising outside the agreed scope of the works. This report does not discharge or release you from your legal obligations and duties to any other person. You are the only one authorized to permit copying or distribution of this report (and then only in its entirety). Any such third parties to whom this report may be circulated rely on the content of the report solely at their own risk.





Intertek Testing Services Taiwan Ltd. 全國公證檢驗股份有限公司 8F., No. 423, Ruiguang Rd., Neihu District, Taipei, 11492, Taiwan, R.O.C. 11492 台北市內湖區瑞光路 423 號 8 樓 Tel: (+886-2) 6602-2888 · 2797-8885 Fax: (+886-2) 6602-2420 www.intertek-twn.com